

Statof Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program Report Date: September 29, 2006

Supervisor _____

Mine Name: Red Hollow

Operator Name: Red Mud Mining Company P.O. Box 1973 1540 North 900 East Beaver, Utah 84713

Inspector(s): Doug Jensen Other Participants: None Permit number: S/053/033 Date: September 13, 2006

Time: 6:30 PM

Mine Status: Inactive	Weather: Clear, warm		
Elements of Inspection	Evaluated	Comment	Enforcement
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, lateral) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control Concurrent Reclamation Backfilling/Grading (trenches, pits, roads highwalls, shafts, drill holes) Water Impoundments Soils Revegetation Air Quality Other Purpose of Inspection: Inspected the site while in the area. 	trol, safety)		
1			

Inspection Summary:

Directions to Site:

The site remains unchanged since my inspection last spring. The area was photographed and gps'd during my last visit therefore I did not complete any further documentation.

Conclusions and Recommendations:

Refer to previous inspection report.

I will continue to monitor the site when I am in the area.

Inspector's Signature trong fensen Date: 9/28/06

dj:pb

cc: Red Mud Mining Company

Russ Schreiner, BLM, St George FO UTU-70004

O:\M053-Washington\S0530033-RedMud\inspections\09142006insp.doc